

How to Order

Part Numbering System

Single Input	Rotary Linear	Stroke	Gauges	Limit Switch	Indicator	Special
1	2	3	4	5	6	7

Base Part #	
55-3000	Pneumatic
56-4000	Electro-Pneumatic Nema 4
56-7000	Electro-Pneumatic Nema 7

4 Gauges	
1	Steel
2	Stainless Steel
3	None

1 Signal Input	
4	3-15
5	4-20
6	Digital
7	Smart

5 Limit Switches	
5	SPDT Mechanical
6	1 Proximity
7	2 Proximity
8	4-20 Potentionmeter
0	None

2 Rotary Linear	
R	Rotary
L	Linier

6 Indicator	
2	Flat

3 Stroke	
2	L-10-80 mm
3	80-150-mm
4	Namur

7 Specials	
S	Special
1	Standard